

Universal Audio Installer for Mac OS X Read Me

Thank you for installing Universal Audio Installer for Mac OS X. This package installs updated Mac OS X drivers and software for all MOTU FireWire, USB, Hybrid, and PCI-424 audio interfaces. This update also contains CueMix FX support for TouchOSC and TouchOSC Layouts 1.0 for MOTU products.

Supported Products:

- 2408mk3
- 24I/O
- 4pre
- 828mk3 (FireWire and Hybrid)
- 828x
- 896mk3 (FireWire and Hybrid)
- 8PRE (FireWire and USB)
- Audio Express
- HD192
- MicroBook II
- Track16
- Traveler-mk3
- UltraLite-mk3 (FireWire and Hybrid)
- Legacy products: 1224, 1296, 2408, 2408mkII, 24i, 308, 828, 828mkII (FireWire and USB), 896, 896HD, MicroBook, Traveler, and the UltraLite.

Supported Operating Systems:

- Mac OS X 10.9
- Mac OS X 10.8
- Mac OS X 10.7
- Mac OS X 10.6

Installation Instructions:

- Double-click 'MOTU Universal Audio Installer.pkg' and follow the on-screen instructions.

Enhancements introduced in version 1.6.60625 (3/17/2014):

- Restored Default Stereo Input and Output module.
- Changed the default value for faders on the MicroBook II to be nominal gain.
- Fixed Phones Assign menu ordering issues for 828mk3 family of products (828mk3, 828mk3 Hybrid, and 828x).

Enhancements introduced in version 1.6.59644 (1/3/2014):

- Added 828x support.

Enhancements introduced in version 1.6.59200 (11/7/2013):

- Improved Mac OS X 10.9 support.
- CueMix FX – FFT analysis window now has mono, stereo maximum, stereo shared, stereo subtract, and stereo split screen view modes.

Enhancements introduced in version 1.6.58373 (8/20/2013):

- Added 8PRE USB support.

Enhancements introduced in version 1.6.57985 (6/24/2013):

- Fixed an issue with MIDI input.

Enhancements introduced in version 1.6.57626 (6/19/2013):

- Improved Mac OS X 10.6 support.

Enhancements introduced in version 1.6.57625 (6/13/2013):

- Aux 1-2 is now the first output stream on MicroBook II.
- Fixed an issue where default output assignment would reset after the computer restarts.
- Fixed an issue where a MIDI Device would be duplicated after the computer restarts.
- Improved CueMix FX OSC support.

We hope you enjoy using your MOTU hardware. We welcome your comments and suggestions.

Sincerely,

Hardware Development Team
www.motu.com/techsupport
www.motu.com/suggestions

©2013 MOTU, Inc.